

# City of Baltimore Wet Weather Consent Decree Smoke and Dyed Water Testing Form

Page 1 of 3

Sewershed : Gwynn Falls

Company : URS

Date : 09/24/2008

Test to be Performed :  
Smoke : X Dyed Water :   

Ground Condition :  
Dry : X Damp :    Wet :   

Supervisor : Ryan Lamont

Manhole ID : S05QQ\_011MH

Test ID : S1032-022041

Notifications (Residents, Fire, 311) :  
Yes

**Field Sketch :** (Show All Manholes with Numbers, Blower Placement Location, Sandbag or Isolation Locations, Street Names, Building Addresses and Locations, Defect Locations and Photograph Numbers)



LEGEND		Defect Code	Defect Description	Defect Code	Defect Description
		SL	Service Lateral	CB	Catch Basin
		TJ	Transition Joint	SD	Storm Ditch
		DD	Driveway Drain	SWMH	Storm Manhole
		WWD	Window Well Drain	MAIN	Main Sewer
		STRD	Stairwell Drain	SANMH	Sewer Manhole
		AD	Area Drain	CO	Cleanout
		DS	Downspout	OTHER	Other
		DSC	Downspout Connection	IOB	Inside of Building
		FD	Foundation Drain		

# City of Baltimore Wet Weather Consent Decree Smoke and Dyed Water Testing Form

Page 2 of 3

Sewershed : Gwynn Falls

Company : URS

Date : 09/24/2008

Test to be Performed :  
Smoke : X Dyed Water :   

Ground Condition :  
Dry : X Damp :    Wet :   

Supervisor : Ryan Lamont


Manhole ID : S05QQ 011MH

Test ID : S1032-022041

Notifications (Residents, Fire, 311) :  
Yes

**Field Sketch :** (Show All Manholes with Numbers, Blower Placement Location, Sandbag or Isolation Locations, Street Names, Building Addresses and Locations, Defect Locations and Photograph Numbers)

ID



Location: N/A; Type: Service Lateral; Smoke: Medium; Status: Private Property


Landscape



Defect



ID



Location: N/A; Type: Cleanout; Smoke: Medium; Status: Private Property

Landscape



Defect





# City of Baltimore Wet Weather Consent Decree Smoke and Dyed Water Testing Form

Page 3 of 3

Sewershed : Gwynn Falls

Company : URS

Date : 09/24/2008

Test to be Performed :  
Smoke : X Dyed Water :   

Ground Condition :  
Dry : X Damp :    Wet :   

Supervisor : Ryan Lamont


Manhole ID : S05QQ 011MH

Test ID : S1032-022041

Notifications (Residents, Fire, 311) :  
Yes

**Field Sketch :** (Show All Manholes with Numbers, Blower Placement Location, Sandbag or Isolation Locations, Street Names, Building Addresses and Locations, Defect Locations and Photograph Numbers)

ID



Location: N/A; Type: Service Lateral; Smoke: Medium; Status: Private Property


Landscape



Defect



ID



Location: N/A; Type: Cleanout; Smoke: Heavy; Status: Private Property

Landscape



Defect

